


# TWEED RIVER ENTRANCE AS AT 2 JULY 2015

**WARNINGS:** *Extreme caution should be used when navigating this entrance.*

*Changes in bed and channel contours could occur rapidly due to waves and currents.*

*Entrance users should not rely on this information, as conditions may have changed since the date of this survey.*

*Seabed contours show average depths in metres below Tweed River Hydro Datum (approx ISLW), not clearance depths.*



## NOTES:

1. Survey information collected by Michel Group Services on 2 July 2015 for the Tweed River Entrance Sand Bypassing Project.
2. Surveys are undertaken every three months to monitor entrance seabed levels.

## TWEED RIVER ENTRANCE SAND BYPASSING PROJECT